

## Extra Charges

**Special Drilling** í í í . Extra Charge of 10%

**Bleaching** í í í í í ... Extra Charge of 10%

## Extra Charge for **production** of the quantity under MOQ

MOQ is determined of diameter (the first measure of double-sized bead).

Measure	Minimum Quantity without Extra Charge	Extra Charge 15%	Extra Charge 30%
4 mm	40 000 pcs	25 000 - 40 000 pcs	15 000 - 25 000 pcs
5 mm	30 000 pcs	20 000 - 30 000 pcs	15 000 - 20 000 pcs
6 - 8 mm	20 000 pcs	15 000 - 20 000 pcs	10 000 - 15 000 pcs
10 mm	20 000 pcs	10 000 - 20 000 pcs	5 000 - 10 000 pcs
12 mm	10 000 pcs	7 000 - 10 000 pcs	5 000 - 7 000 pcs
14 mm	8 000 pcs	6 000 - 8 000 pcs	4 000 - 6 000 pcs
15 - 18 mm	7 000 pcs	5 000 - 7 000 pcs	3 000 - 5 000 pcs
over 20 mm	6 000 pcs	4 000 - 6 000 pcs	2 000 - 4 000 pcs

## Extra Charge for **colouring** of the quantity under MOQ

MOQ is determined of diameter (the first measure of double-sized bead).

The raw beads must be on the stock.

Measure	Minimum Quantity without Extra Charge	Extra Charge 15%	Extra Charge 30%
4 mm	40 000 pcs	25 000 - 40 000 pcs	15 000 - 25 000 pcs
5 mm	30 000 pcs	20 000 - 30 000 pcs	15 000 - 20 000 pcs
6 - 8 mm	20 000 pcs	10 000 - 20 000 pcs	5 000 - 10 000 pcs
10 - 12 mm	10 000 pcs	6 000 - 10 000 pcs	3 000 - 6 000 pcs
14 - 18 mm	5 000 pcs	4 000 - 5 000 pcs	2 000 - 4 000 pcs
over 20 mm	2 000 pcs	1 500 - 2 000 pcs	1 000 - 1 500 pcs